Executive Summary – Enforcement Matter – Case No. 48394 E. I. du Pont de Nemours and Company RN100542711 Docket No. 2014-0377-AIR-E

Order Type:

Findings Agreed Order

Findings Order Justification:

People or environmental receptors have been exposed to pollutants which exceed levels that are protective.

Media:

AIR

Small Business:

No

Location(s) Where Violation(s) Occurred:

Dupont Sabine River Works, 3055 Farm-to-Market Road 1006, Orange, Orange County

Type of Operation:

Chemical manufacturing plant

Other Significant Matters:

Additional Pending Enforcement Actions: Yes, Docket No. 2014-0868-AIR-E

Past-Due Penalties: No

Other: N/A

Interested Third-Parties: None

Texas Register Publication Date: July 25, 2014

Comments Received: No

Penalty Information

Total Penalty Assessed: \$25,000

Amount Deferred for Expedited Settlement: \$0 Amount Deferred for Financial Inability to Pay: \$0

Total Paid to General Revenue: \$12,500

Total Due to General Revenue: \$0

Payment Plan: N/A

SEP Conditional Offset: \$12,500

Name of SEP: Texas Congress of Parents and Teachers dba Texas PTA (Third-

Party Pre-Approved)

Compliance History Classifications:

Person/CN - Satisfactory Site/RN - Satisfactory

Major Source: Yes

Statutory Limit Adjustment: \$25,000 Applicable Penalty Policy: September 2011

Executive Summary – Enforcement Matter – Case No. 48394 E. I. du Pont de Nemours and Company RN100542711 Docket No. 2014-0377-AIR-E

Investigation Information

Complaint Date(s): N/A
Complaint Information: N/A

Date(s) of Investigation: February 4, 2014

Date(s) of NOE(s): February 28, 2014

Violation Information

Failed to prevent unauthorized emissions. Since the emissions event could have been avoided with better operation and maintenance practices, the Respondent is precluded from asserting an affirmative defense under 30 Tex. Admin. Code § 101.222 [30 Tex. Admin. Code §§ 116.115(b)(2)(F), 116.115(c), and 122.143(4), Tex. Health & Safety Code § 382.085(b), New Source Review Permit No. 20204, Special Conditions No. 1, and Federal Operating Permit No. 02055, General Terms and Conditions and Special Terms and Conditions No. 12].

Corrective Actions/Technical Requirements

Corrective Action(s) Completed:

N/A

Technical Requirements:

- 1. The Order will require the Respondent to implement and complete a Supplemental Environmental Project ("SEP"). (See SEP Attachment A)
- 2. The Order will also require the Respondent to:
- a. Within 30 days, implement measures and/or procedures to prevent the recurrence of emissions events due to the same cause as the emissions event that occurred on November 12, 2013 (Incident No. 190675); and
- b. Within 45 days, submit written certification to demonstrate compliance with Ordering Provision a.

Litigation Information

Date Petition(s) Filed: N/A Date Answer(s) Filed: N/A SOAH Referral Date: N/A Hearing Date(s): N/A

Settlement Date: N/A

Executive Summary – Enforcement Matter – Case No. 48394 E. I. du Pont de Nemours and Company RN100542711 Docket No. 2014-0377-AIR-E

Contact Information

TCEQ Attorney: N/A

TCEQ Enforcement Coordinator: Farhaud Abbaszadeh, Enforcement Division, Enforcement Team 4, MC 149, (512) 239-0779; Candy Garrett, Enforcement Division, MC 219, (512) 239-1456

TCEQ SEP Coordinator: Stuart Beckley, SEP Coordinator, Enforcement Division,

MC 219, (512) 239-3565

Respondent: John R. Laughlin, Site Manager, E. I. du Pont de Nemours and

Company, P.O. Box 1089, Orange, Texas 77631

Steven Barger, Environmental Engineer, E. I. du Pont de Nemours and Company, P.O.

Box 1089, Orange, Texas 77631 **Respondent's Attorney:** N/A

Attachment A

Docket Number: 2014-0377-AIR-E

SUPPLEMENTAL ENVIRONMENTAL PROJECT

Respondent:	E. I. du Pont de Nemours and Company
Penalty Amount:	Twenty-Five Thousand Dollars (\$25,000)
SEP Offset Amount:	Twelve Thousand Five Hundred Dollars (\$12,500)
Type of SEP:	Contribution to a Third-Party Pre-Approved SEP
Third-Party Administrator:	Texas Congress of Parents and Teachers dba Texas PTA
Project Name:	Texas PTA Clean School Bus Replacement Program
Location of SEP:	Statewide, with preference for Texas Air Quality Control Region 106: Southern Louisiana - Southeast Texas

The Texas Commission on Environmental Quality ("TCEQ") agrees to offset a portion of the administrative penalty amount assessed in this Agreed Order for the Respondent to contribute to a Supplemental Environmental Project ("SEP"). The SEP Offset Amount is set forth above and such offset is conditioned upon completion of the project in accordance with the terms of this Attachment A.

1. Project Description

a. Project

The Respondent shall contribute the SEP Offset Amount to the Third-Party Administrator named above. The contribution will be to the **Texas Congress of Parents and Teachers dba Texas PTA** for the *Texas PTA Clean School Bus Replacement Program*. The contribution will be used in accordance with the SEP between the Third-Party Administrator and the TCEQ (the "Project"). Specifically, the contribution will be used to reduce nitrogen oxides, volatile organic compounds, carbon monoxide, and particulate matter emissions by replacing older diesel buses with newer buses that meet more stringent emission standards. The Third-Party Administrator shall use the SEP Offset Amount for up to 100% of the purchase price of a model year 2010 or newer bus to replace a diesel school bus that is model year 2002 or older. The SEP will be done in accordance with all federal, state, and local environmental laws and regulations.

All dollars contributed will be used solely for the direct cost of the Project, including but not limited to supplies, materials, and equipment. Any portion of this contribution that is not spent on the specifically identified SEP may, at the discretion of the Executive Director ("ED"), be applied to another pre-approved SEP.

E. I. du Pont de Nemours and Company Agreed Order - Attachment A

The Respondent's signature affixed to this Agreed Order certifies that it has no prior commitment to make this contribution and that it is being contributed solely in an effort to settle this enforcement action. The Respondent shall not profit in any manner from this SEP.

b. Environmental Benefit

This SEP will directly benefit air quality by reducing harmful exhaust emissions which contribute to the formation of ozone and may cause or exacerbate a number of respiratory diseases, including asthma. In addition, by encouraging less school bus idling, this SEP contributes to public awareness of environmental matters.

c. Minimum Expenditure

The Respondent shall contribute at least the SEP Offset Amount to the Third-Party Administrator and comply with all other provisions of this SEP.

2. Performance Schedule

Within 30 days after the effective date of this Agreed Order, the Respondent must contribute the SEP Offset Amount to the Third-Party Administrator. The Respondent shall make the check payable to **Texas Congress of Parents and Teachers SEP** and shall mail the contribution with a copy of the Agreed Order to:

Texas PTA 408 West 11th Street Austin, Texas 78701

3. Records and Reporting

Concurrent with the payment of the SEP Offset Amount, the Respondent shall provide the Enforcement Division SEP Coordinator with a copy of the check and transmittal letter indicating full payment of the SEP Offset Amount due to the Third-Party Administrator. The Respondent shall mail a copy of the check and transmittal letter to:

> Texas Commission on Environmental Quality Enforcement Division Attention: SEP Coordinator, MC 219 P.O. Box 13087 Austin, Texas 78711-3087

E. I. du Pont de Nemours and Company Agreed Order - Attachment A

4. Failure to Fully Perform

If the Respondent does not perform its obligations under this Attachment A, including full expenditure of the SEP Offset Amount and submittal of the required reporting described in Sections 2 and 3 above, the ED may require immediate payment of all or part of the SEP Offset Amount.

In the event the ED determines that the Respondent failed to fully implement and complete the Project, the Respondent shall remit payment for all or a portion of the SEP Offset Amount, as determined by the ED, and as set forth in the attached Agreed Order. After receiving notice of failure to complete the SEP, the Respondent shall include the docket number of the attached Agreed Order and a note that the enclosed payment is for the reimbursement of a SEP; shall make the check payable to "Texas Commission on Environmental Quality;" and shall mail it to:

Texas Commission on Environmental Quality Litigation Division Attention: SEP Coordinator, MC 175 P.O. Box 13087 Austin, Texas 78711-3087

5. Publicity

Any public statements concerning this SEP made by or on behalf of the Respondent, must include a clear statement that **the Project was performed as part of the settlement of an enforcement action brought by the TCEQ**. Such statements include advertising, public relations, and press releases.

6. Clean Texas Program

The Respondent shall not include this SEP in any application made to TCEQ under the "Clean Texas" (or any successor) program(s). Similarly, the Respondent may not seek recognition for this contribution in any other state or federal regulatory program.

7. Other SEPs by TCEQ or Other Agencies

The SEP Offset Amount identified in this Agreed Order has not been, and shall not be, included as a SEP for the Respondent under any other Agreed Order negotiated with the TCEQ or any other agency of the state or federal government.

Penalty Calculation Worksheet (PCW) PCW Revision August 3, 2011 Assigned 4-Mar-2014 PCW 10-Mar-2014 Screening 10-Mar-2014 **EPA Due** RESPONDENT/FACILITY INFORMATION Respondent E. I. du Pont de Nemours and Company Reg. Ent. Ref. No. RN100542711 Facility/Site Region 10-Beaumont Major/Minor Source Major **CASE INFORMATION** Enf./Case ID No. 48394 No. of Violations Docket No. 2014-0377-AIR-E Order Type Findings Government/Non-Profit No Media Program(s) Air Multi-Media Enf. Coordinator Farhaud Abbaszadeh EC's Team Enforcement Team 4 Maximum Admin. Penalty \$ Limit Minimum \$25,000 Penalty Calculation Section TOTAL BASE PENALTY (Sum of violation base penalties) \$25,000 Subtotal 1 ADJUSTMENTS (+/-) TO SUBTOTAL 1 Subtotals 2-7 are obtained by multiplying the Total Base Penalty (Subtotal 1) by the indicated percentage. Compliance History 100.0% Enhancement Subtotals 2, 3, & 7 \$25,000 Enhancement for four NOVs with same/similar violations, one NOV with dissimilar violations, 13 orders with a denial of liability, and two orders Notes without a denial of liability. Culpability No 0.0% Enhancement Subtotal 4 \$0 Notes The Respondent does not meet the culpability criteria. Good Faith Effort to Comply Total Adjustments Subtotal 5 \$0 **Economic Benefit** 0.0% Enhancement* Subtotal 6 \$0 Total EB Amounts \$101 *Capped at the Total EB \$ Amount Approx. Cost of Compliance SUM OF SUBTOTALS 1-7 \$50,000 Final Subtotal OTHER FACTORS AS JUSTICE MAY REQUIRE 0.0% \$0 Adjustment Reduces or enhances the Final Subtotal by the indicated percentage. Notes Final Penalty Amount \$50,000 STATUTORY LIMIT ADJUSTMENT Final Assessed Penalty \$25,000 \$0 0.0% Reduction Adjustment Reduces the Final Assessed Penalty by the indicated percentage. (Enter number only; e.g. 20 for 20% reduction.) No deferral is recommended for Findings Orders. Notes

\$25,000

PAYABLE PENALTY

PCW

Respondent E. I. du Pont de Nemours and Company

Case ID No. 48394

Reg. Ent. Reference No. RN100542711

Media [Statute] Air

Enf. Coordinator Farhaud Abbaszadeh

Policy Revision 3 (September 2011)

PCW Revision August 3, 2011

Compliance History Worksheet

Component	Number of	Enter Number Here	Ad
NOVs	Written notices of violation ("NOVs") with same or similar violations as those in the current enforcement action (number of NOVs meeting criteria)	4	20
	Other written NOVs	1	2
	Any agreed final enforcement orders containing a denial of liability (number of orders meeting criteria)	13	26
Orders	Any adjudicated final enforcement orders, agreed final enforcement orders without a denial of liability, or default orders of this state or the federal government, or any final prohibitory emergency orders issued by the commission	r i	50
Judgments	Any non-adjudicated final court judgments or consent decrees containing a denial of liability of this state or the federal government (number of judgements or consent decrees meeting criteria)	0	0
and Consent Decrees	Any adjudicated final court judgments and default judgments, or non-adjudicated final court judgments or consent decrees without a denial of liability, of this state or the federal government	i.	0
Convictions	Any criminal convictions of this state or the federal government (number of counts)	0	0
Emissions	Chronic excessive emissions events (number of events)	0	0
Audits	Letters notifying the executive director of an intended audit conducted under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 (number of audits for which notices were submitted)		0
	Disclosures of violations under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 (number of audits for which violations were disclosed)	0	0
	Ple	ease Enter Yes or No	
	Environmental management systems in place for one year or more	No	0
	Valuntary on site compliance accessments conducted by the executive director		

	Environmental management systems in place for one year or more	No	0%
	Voluntary on-site compliance assessments conducted by the executive director under a special assistance program	No	0%
	Participation in a voluntary pollution reduction program	No	0%
4	Early compliance with, or offer of a product that meets future state or federal government environmental requirements	No	0%

Adjustment Percentage (Subtotal 2) | 332%

>> Repeat Violator (Subtotal 3)

No

Adjustment Percentage (Subtotal 3)

0%

>> Compliance History Person Classification (Subtotal 7)

Satisfactory Performer

Adjustment Percentage (Subtotal 7)

0%

>> Compliance History Summary

Compliance History Notes

Enhancement for four NOVs with same/similar violations, one NOV with dissimilar violations, 13 orders with a denial of liability, and two orders without a denial of liability.

Total Compliance History Adjustment Percentage (Subtotals 2, 3, & 7)

>> Final Compliance History Adjustment

Final Adjustment Percentage *capped at 100%

100%

Respondent: E. I. du Pront de Remours and Company Case ID Not. 48393 Reg. Ent. Reference Not. RN10052711 Medial [Statute] Enf. Coordinator Farbaud Abborated Violation Number Violation Number Rule Cita(s) Rule Cit	Screening Date	10-Mar-2014 D o	cket No. 2014-0377-AIR-E	PCW
Reg. Ent. Reference No. Nilo0542711 Media [Statute] Enf. Coordinator Fahaud Abbaszadeh Violation Number Rule Cite(s) Rule				
Finf. Coordinator - Zamaud Abbaszaden Violation Number Rule Cite(a) Rule Cite(a) Rule Cite(a) Rule Cite(b) Rule Cite(a) Rule Cite(b) Rule Cite(b) Rule Cite(c) R				PCW Revision August 3, 2011
Violation Number Rule Cite(s) R				
Rule Cite(s) Ru	출시자 · · · · · · · · · · · · · · · · · · ·			
Conditions No. 1, and Federal Operating Permit No. 02055, General Ferms and Contritions and Special Terms and Conditions No. 12 Falled to prevent unauthorized emissions. Specifically, title Respondent released 14,435 pounds (18s) of grospen, 2018 for propress, and 371 lbs of methacrylic acid from the Dump Valve Stacks, Emission Point Number PLUM-G, during an emissions sevent (Clinical No. 190675) that accurred on November 12, 2013 and lasted 13 minutes. This event accurred when the sealing edge of the cone plant was not pripally sealed and a torque went with a torque specification of 75 foot pounds was used on the valve rather than the required torque of 75 foot pounds was used on the valve rather than the required torque of 75 foot pounds was used on the valve rather than the required torque of 75 foot pounds was used on the valve rather than the required torque of 75 foot pounds was used on the valve rather than the required torque of 75 foot pounds was used on the valve rather than the required torque of 75 foot pounds was used on the valve rather than the required torque of 75 foot pounds was used on the valve rather than the required torque of 75 foot pounds was used on the valve rather than the required torque of 75 foot pounds was used on the valve rather than the required torque of 75 foot pounds was used on the valve rather than the required torque of 75 foot pounds was used on the valve rather than the required torque of 75 foot pounds was used on the valve rather than the required torque of 75 foot pounds was used on the valve rather than the required torque of 75 foot pounds was used on the valve rather than the required torque of 75 foot pounds was used on the valve rather than the required torque of 75 foot pounds was used on the valve rather than the required torque of 75 foot pounds was used on the valve rather than the required torque of 75 foot pounds was used on the valve rather than the required torque of 75 foot pounds was used on the valve rather than the required torque of 75 foot pounds	7,010,011,110,110,011		2)(F), 116.115(c), and 122.14	B(4), Tex.
Conditions and Special Terms and Conditions No. 12	Rule Cite(s)			
14,435 pounds (*Ibs*) of gaseous ethylene, 1,222 lbs of propane, and 371 lbs of methacrylic add from the Dumy York Stocker, Emission Point Number PLUM-G, during an emissions event (Incident No. 190675) that occurred on November 12, 2013 and lated 11 minutes. This event occurred when the sating edge of the cone joint was not properly sealed and a forque wrench with a torque specification of 75 fold pounds was used on the valve rather than the required forque specification of 85 to 10 fold pounds with resulted in 3 to 10 feet new to the sating the sating of the fold purpose of the fold of the sating of the sating of the fold of the sating				
methacrylic acid from the Dump Valve Stacks, Emission Point flumber PLIM-G, during an emissions, event fucient No. 1965 that occurred on November 12, 2013 and lasted 11 minutes. This event occurred when the sealing edge of the cone joint was not properly scaled and a torque wersh with a torque specification of 75 foot pounds was used on the valve rather than the required torque specification of 85 to 110 foot pounds with restrict on 19 et fire near the Pressure Energy Recovery Process valves. The unit was shut down and the emissions from the unit were relosed to the throughers. Since the emissions event could have been avoided with better operation and maniteriance practices, the Respondent is precluded from asserting an effirmative science under 30 feet. Admin. Code 1 methods with the company of the comp				
Violation Description Violation Description Violation Description Violation Description Violation Description Violation Description Or 75 foot pounds was used on the valve rather than the required torque specification of 75 foot pounds was used on the valve rather than the required torque specification of 85 to 110 froot pounds which restured in a jet fire near the Pressure Energy Recovery Process valves. The unit was shut down and the emissions from the unit were released to the atmosphere. Since the emissions event could have been avoided with setter operation and mantenance practices, the Respondent is precluded from asserting an affirmative defense under 30 feet. Admin. Code 9 September 101.2222 Base Penalty 925,000 September 101.2222 Base Penalty 925,000 Percent 100.0% Percent 100.0% Matrix Property and Human Health Matrix Harm Moderate Minor Percent 100.0% Matrix Properties Matrix Property and Human Health or the environment has been exposed to pollutants which exceed levels that are protective of human health or environmental receptors as a result of the violation. Violation Events Number of Violation Events 1 Number of violation days disaffering and the violation of the violation days was a second of the violation of t	-			**************************************
Violation Description Cone joint was not properly select and a torque wench with a torque specification of 75 foot pounds was used on the valve rather than the required torque specification of 85 to 110 foot pounds which resulted in a jet fire near the Pressure Energy Recovery Process valves. The unit was shut down and the emissions revent could have been avoided with better operation and manitemance practices, the Respondent is precluded from asserting an affirmative defense under 30 fex. Admin. Code § Sease Penalty \$25,000		ting the control of t		111111111111111111111111111111111111111
specification of 85 to 110 foot pounds which resulted in a jet fire near the Pressure frency Recovery Process valves. The unit was shut down and the emissions from the unit were released to the atmosphere. Since the emissions sevent could have been avoided with better operation and maintenance practices, the Respondent is precluded from asserting an affirmative defense under 30 Tex. Admin. Code § 101.222. Base Penalty		cone joint was not properly sealed and a	torque wrench with a torque	specification
Energy Recovery Process valves. The unit was shut down and the emissins from the unit were released to the atmosphere. Since the emissions event could have been avoided with better operation and maintenance practices, the Respondent is precluded from asserting an affirmative defense under 30 Tex. Admin. Code § \$25,000	Violation Description	Fig. 1. Some and the second of the second	FIRST CONTRACTOR CONTR	
been avoided with better operation and maintenance practices, the Respondent is precluded from asserting an affirmative defense under 30 Tex. Admin. Code § 101.222. Base Penalty \$25,000 >> Environmental, Property and Human Health Matrix Harm Release Major Moderate Minor Actual X Potential Percent 100.0% >> Percent 100.0% >> Percent 100.0% Matrix Human health or the environment has been exposed to pollutants which exceed levels that are protective of human health or environmental receptors as a result of the violation. Adjustment 50 \$25,000 Violation Events Number of Violation Events 1 Number of violation days Adely xeekly X monthly weekly xeekly x annual single event 1 secommended. Good Faith Efforts to Comply 0.0% Reduction 940 to DPN/Settlement Offer Extraordinary Ordinary Ordin		Energy Recovery Process valves. The u	nit was shut down and the em	issions from
Seconomic Benefit (EB) for this violation Statutory Limit Test Seconomic Benefit (EB) for this violation				
Seconomic Benefit (EB) for this violation Statutory Limit Test Seconomic Benefit (EB) for this violation Statutory Limit Test Seconomic Benefit (EB) for this violation Statutory Limit Test Seconomic Benefit (EB) for this violation Statutory Limit Test Seconomic Benefit (EB) for this violation Statutory Limit Test Statuto				n. Code §
>> Environmental, Property and Human Health Matrix Harm Release Major Moderate Minor			ts222x	
OR Release Major Moderate Minor Actual X Potential Percent 100.0% >>Programmatic Matrix Faisification Major Moderate Minor Percent 0.0% Matrix Notes Human health or the environment has been exposed to pollutants which exceed levels that are protective of human health or environmental receptors as a result of the violation. Adjustment			В	ase Penalty \$25,000
Release Major Moderate Minor Actual X Potential Percent 100.0% >> Programmatic Matrix Falsification Major Moderate Minor Percent 0.0% Matrix Human health or the environment has been exposed to pollutants which exceed levels that are protective of human health or environmental receptors as a result of the violation. Adjustment \$0 \$25,000 Violation Events Number of Violation Events 1 1 Number of violation days Weekly weekly weekly with an x senion and a single event 1	>> Environmental, Proper	ty and Human Health Matrix		
OR Actual X Potential Percent 100.0% >> Programmatic Matrix Falsification Major Moderate Minor Percent 0.0% Matrix Human health or the environment has been exposed to pollutants which exceed levels that are protective of human health or environmental receptors as a result of the violation. Adjustment	Release			
>> Programmatic Matrix Falsification Major Moderate Minor Percent 0.0% Matrix Human health or the environment has been exposed to pollutants which exceed levels that are protective of human health or environmental receptors as a result of the violation. **Adjustment** **Adjustment** **Soo **S25,000 Violation Events** Number of Violation Events** Number of Violation Events** **Number of Violation Events** **Ood daily weekly monthly mountain annual annu	OR Actual			
Falsification Major Moderate Minor Percent 0.0% Matrix Notes Human health or the environment has been exposed to pollutants which exceed levels that are protective of human health or environmental receptors as a result of the violation. Adjustment 40 \$25,000 Violation Events Number of Violation Events 1 1 Number of violation days Mark only one with an x Quarterly Semiannual annual single event Semiannual annual annual single event Semiannual annual annual single event Semiannual annual annua	Potential		Percent 100.0	<u>%</u>
Matrix Notes Human health or the environment has been exposed to pollutants which exceed levels that are protective of human health or environmental receptors as a result of the violation. Adjustment				
Matrix Notes	Falsification Falsification	Major Moderate Minor	Percent 0.00	76]
Notes protective of human health or environmental receptors as a result of the violation. Adjustment			<u> </u>	
Adjustment \$0 \$25,000	1004014010160101111111 M			N 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Violation Events Number of Violation Events 1	Notes protec	tive of human health or environmental re	ceptors as a result of the viola	tion.
Number of Violation Events Number of Violation Events 1			Adjustment	\$0
Number of Violation Events Number of Violation Events 1				\$25,000
Number of Violation Events 1 1 Number of violation days daily	V/:_1E: =:E			
daily	violation events			
weekly monthly quarterly semiannual annual single event One daily event is recommended. Sood Faith Efforts to Comply O.0% Reduction \$0 Before NOV NOV to EDPRP/Settlement Offer Extraordinary Ordinary Ordinary N/A x (mark with x) The Respondent does not meet the good faith criteria for this violation. Violation Subtotal \$25,000 Economic Benefit (EB) for this violation Statutory Limit Test \$25,000	Number of	violation Events 1	1 Number of violation	on days
mark only one with an x monthly quarterly semiannual annual single event		daily x		
Good Faith Efforts to Comply Before NOV NOV to EDPRP/Settlement Offer Extraordinary Ordinary N/A x (mark with x) Notes The Respondent does not meet the good faith criteria for this violation. Violation Subtotal \$25,000 \$25,000 \$25,000				
Semiannual annual single event One daily event is recommended. One daily event is recommended. Sometimes and the first sto Comply annual single event of the single		· .	Violation B	ase Penalty \$25,000
Good Faith Efforts to Comply One daily event is recommended. Sood Faith Efforts to Comply Before NOV NOV to EDPRP/Settlement Offer Extraordinary Ordinary N/A x (mark with x) The Respondent does not meet the good faith criteria for this violation. Violation Subtotal \$25,000 Economic Benefit (EB) for this violation Statutory Limit Test	With all X	semiannual		
Good Faith Efforts to Comply Before NOV NOV to EDPRP/Settlement Offer				
Good Faith Efforts to Comply Before NOV NOV to EDPRP/Settlement Offer	F			
Extraordinary Ordinary N/A x (mark with x) Notes The Respondent does not meet the good faith criteria for this violation. Violation Subtotal \$25,000 Economic Benefit (EB) for this violation Statutory Limit Test		One daily event is reco	mmended.	
Extraordinary Ordinary N/A x (mark with x) Notes The Respondent does not meet the good faith criteria for this violation. Violation Subtotal \$25,000 Economic Benefit (EB) for this violation Statutory Limit Test	Good Faith Efforts to Com	oly 0.0% Reduction		\$0
Ordinary N/A x (mark with x) The Respondent does not meet the good faith criteria for this violation. Violation Subtotal \$25,000 Economic Benefit (EB) for this violation Statutory Limit Test			P/Settlement Offer	
N/A x (mark with x) Notes The Respondent does not meet the good faith criteria for this violation. Violation Subtotal \$25,000 Economic Benefit (EB) for this violation Statutory Limit Test			e transferitike	
Violation Subtotal \$25,000 Economic Benefit (EB) for this violation Statutory Limit Test		N/A x (mark with x)		-
Violation Subtotal \$25,000 Economic Benefit (EB) for this violation Statutory Limit Test		NOTECH	 *** *********************************	or
Economic Benefit (EB) for this violation Statutory Limit Test				
			Violati	on Subtotal \$25,000
Estimated EB Amount \$101 Violation Final Penalty Total \$50,000	Economic Benefit (EB) for	this violation	Statutory Lin	iit Test
Estimated to Amount 1511 Floridity 10tal \$50,000	Estimat	ed EB Amount \$101	Violation Final Pe	enalty Total \$50,000
This violation Final Assessed Penalty (adjusted for limits) \$25,000		This violation Final	Assessed Penalty (adjusted	1 for limits) \$25,000

Media Violation No.						Percent Interest	Years of Depreciation
violation no.	1					5.0	15
	Item Cost	Date Required	Final Date	Yrs	Interest Saved	Onetime Costs	EB Amount
Item Description	No commas or \$						
Delayed Costs							
Equipment				0.00	\$0	\$0	\$0
Buildings				0,00	\$0	\$0	\$0
Other (as needed)	<u> </u>			0.00	\$0	\$0	\$0
Engineering/construction				0.00	\$0	\$0	\$0
Land				0.00	\$0	n/a	\$0
Record Keeping System				0.00	\$0	n/a	<u>\$0</u>
Training/Sampling	L	4		0.00	\$0 \$0	n/a n/a	\$0 \$0
Damediation (Discussed							
Remediation/Disposal				0.00		*******************	
Permit Costs Other (as needed)	B	The second secon		0.00 0.81 proced	\$0 \$101 dures to prevent t	n/a n/a he recurrence of em	\$0 \$101 ilssions events
Permit Costs Other (as needed) Notes for DELAYED costs	Estimated co	st to implement me same cause as in occured.	neasures and/o ncident No. 190 The Final Date	0.00 0.81 r proced 675. The	\$0 \$101 dures to prevent t ne Date Required estimated date of	n/a n/a he recurrence of em is the date the emis compliance.	\$0 \$101 dissions events sions event
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs	Estimated co	st to implement me same cause as in occured.	neasures and/o ncident No. 190 The Final Date	0.00 0.81 proced 675. The is the	\$0 \$101 dures to prevent t ne Date Required estimated date of ng item (except	n/a n/a he recurrence of em is the date the emis compliance. for one-time avoid	\$0 \$101 dissions events sions event
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal	Estimated co	st to implement me same cause as in occured.	neasures and/o ncident No. 190 The Final Date	0.00 0.81 r proced 675. The is the enterin	\$0 \$101 dures to prevent the Date Required estimated date of og item (except \$0	n/a n/a he recurrence of em is the date the emis- compliance. for one-time avoid	\$0 \$101 dissions events sions event ded costs)
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal Personnel	Estimated co	st to implement me same cause as in occured.	neasures and/o ncident No. 190 The Final Date	0.00 0.81 proced 675. The is the enterin 0.00 0.00	\$0 \$101 dures to prevent the Date Required estimated date of the office	n/a n/a n/a he recurrence of em is the date the emis compliance. for one-time avoic \$0 \$0	\$0 \$101 issions events sions event led costs) \$0 \$0
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal Personnel spection/Reporting/Sampling	Estimated co	st to implement me same cause as in occured.	neasures and/o ncident No. 190 The Final Date	0.00 0.81 r proced 675. The s is the enterin 0.00 0.00 0.00	\$0 \$101 Jures to prevent the Date Required estimated date of significant signi	n/a n/a n/a he recurrence of em is the date the emis compliance. for one-time avoid \$0 \$0 \$0 \$0	\$0 \$101 sissions events sions event led costs) \$0 \$0 \$0
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal Personnel spection/Reporting/Sampling Supplies/equipment	Estimated co	st to implement me same cause as in occured.	neasures and/o ncident No. 190 The Final Date	0.00 0.81 r proced 675. The is the enterin 0.00 0.00 0.00	\$0 \$101 dures to prevent the Date Required estimated date of significant (except \$0 \$0 \$0 \$0 \$0	n/a n/a n/a he recurrence of em is the date the emis compliance. for one-time avoid \$0 \$0 \$0 \$0 \$0	\$0 \$101 sissions events sions event ded costs) \$0 \$0 \$0
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal Personnel spection/Reporting/Sampling Supplies/equipment Financial Assurance [2]	Estimated co	st to implement me same cause as in occured.	neasures and/o ncident No. 190 The Final Date	0.00 0.81 proced 675. The is the enterin 0.00 0.00 0.00 0.00	\$0 \$101 dures to prevent the Date Required estimated date of ogitem (except \$0 \$0 \$0 \$0	n/a n/a n/a he recurrence of em is the date the emis compliance. for one-time avoid \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$101 dissions events sions event led costs) \$0 \$0 \$0 \$0
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal Personnel spection/Reporting/Sampling Supplies/equipment Financial Assurance [2] ONE-TIME avoided costs [3]	Estimated co	st to implement me same cause as in occured.	neasures and/o ncident No. 190 The Final Date	0.00 0.81 proced 675. The is the enterin 0.00 0.00 0.00 0.00 0.00	\$0 \$101 dures to prevent the Date Required estimated date of the second	n/a n/a n/a he recurrence of em is the date the emis compliance. for one-time avoid \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$101 ilssions events sions event led costs) \$0 \$0 \$0 \$0 \$0
Permit Costs Other (as needed) Notes for DELAYED costs Avoided Costs Disposal Personnel spection/Reporting/Sampling Supplies/equipment Financial Assurance [2]	Estimated co	st to implement me same cause as in occured.	neasures and/o ncident No. 190 The Final Date	0.00 0.81 proced 675. The is the enterin 0.00 0.00 0.00 0.00	\$0 \$101 dures to prevent the Date Required estimated date of ogitem (except \$0 \$0 \$0 \$0	n/a n/a n/a he recurrence of em is the date the emis compliance. for one-time avoid \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$101 dissions events sions event led costs) \$0 \$0 \$0 \$0

To request a more accessible version of this report, please contact the TCEQ Help Desk at (512) 239-4357.



Compliance History Report

PUBLISHED Compliance History Report for CN600128284, RN100542711, Rating Year 2013 which includes Compliance History (CH) components from September 1, 2008, through August 31, 2013.

Customer, Respondent,

CN600128284, E. I. du Pont de Nemours Classification: SATISFACTORY

Rating: 7.99

or Owner/Operator:

and Company

Classification: SATISFACTORY

Rating: 19.38

Regulated Entity:

RN100542711, DUPONT SABINE RIVER WORKS

Complexity Points:

49

Repeat Violator: NO

CH Group:

05 - Chemical Manufacturing

Location:

3055 FARM-TO-MARKET ROAD 1006 ORANGE, TEXAS 77630-8045, ORANGE COUNTY

TCEQ Region:

REGION 10 - BEAUMONT

ID Number(s):

AIR OPERATING PERMITS ACCOUNT NUMBER OC0007J **AIR OPERATING PERMITS PERMIT 1896 AIR OPERATING PERMITS PERMIT 1898 AIR OPERATING PERMITS PERMIT 1900** AIR OPERATING PERMITS PERMIT 1996 **AIR OPERATING PERMITS PERMIT 2055 AIR OPERATING PERMITS PERMIT 2331**

POLLUTION PREVENTION PLANNING ID NUMBER

P00193

INDUSTRIAL AND HAZARDOUS WASTE SOLID WASTE

REGISTRATION # (SWR) 30019

AIR NEW SOURCE PERMITS REGISTRATION 72030

AIR NEW SOURCE PERMITS PERMIT 914

AIR NEW SOURCE PERMITS REGISTRATION 1423

AIR NEW SOURCE PERMITS PERMIT 1423B

AIR NEW SOURCE PERMITS PERMIT 2004

AIR NEW SOURCE PERMITS PERMIT 2490 AIR NEW SOURCE PERMITS PERMIT 7021

AIR NEW SOURCE PERMITS REGISTRATION 10447

AIR NEW SOURCE PERMITS REGISTRATION 12967

AIR NEW SOURCE PERMITS PERMIT 17157

AIR NEW SOURCE PERMITS PERMIT 21236

AIR NEW SOURCE PERMITS REGISTRATION 23646

AIR NEW SOURCE PERMITS REGISTRATION 25167

AIR NEW SOURCE PERMITS REGISTRATION 26325

AIR NEW SOURCE PERMITS REGISTRATION 28148

AIR NEW SOURCE PERMITS REGISTRATION 36046

AIR NEW SOURCE PERMITS REGISTRATION 41263

AIR NEW SOURCE PERMITS REGISTRATION 44528 AIR NEW SOURCE PERMITS REGISTRATION 47671

AIR NEW SOURCE PERMITS REGISTRATION 71863

AIR NEW SOURCE PERMITS PERMIT 49076

AIR NEW SOURCE PERMITS REGISTRATION 70647 AIR NEW SOURCE PERMITS REGISTRATION 71054

AIR NEW SOURCE PERMITS REGISTRATION 56781

AIR NEW SOURCE PERMITS REGISTRATION 55710

AIR NEW SOURCE PERMITS REGISTRATION 72443

AIR NEW SOURCE PERMITS REGISTRATION 56055

AIR NEW SOURCE PERMITS REGISTRATION 109695

AIR NEW SOURCE PERMITS REGISTRATION 76581

AIR NEW SOURCE PERMITS REGISTRATION 76580

AIR NEW SOURCE PERMITS REGISTRATION 76690

AIR OPERATING PERMITS PERMIT 1895

AIR OPERATING PERMITS PERMIT 1897

AIR OPERATING PERMITS PERMIT 1899

AIR OPERATING PERMITS PERMIT 1901

AIR OPERATING PERMITS PERMIT 2001

AIR OPERATING PERMITS PERMIT 2074

AIR OPERATING PERMITS PERMIT 1882

INDUSTRIAL AND HAZARDOUS WASTE EPA ID

TXD008079642

INDUSTRIAL AND HAZARDOUS WASTE PERMIT 50230

AIR NEW SOURCE PERMITS PERMIT 9629

AIR NEW SOURCE PERMITS PERMIT 914A

AIR NEW SOURCE PERMITS PERMIT 1423A

AIR NEW SOURCE PERMITS PERMIT 1423C

AIR NEW SOURCE PERMITS PERMIT 2116

AIR NEW SOURCE PERMITS PERMIT 5745

AIR NEW SOURCE PERMITS PERMIT 9176

AIR NEW SOURCE PERMITS REGISTRATION 11434

AIR NEW SOURCE PERMITS REGISTRATION 16327

AIR NEW SOURCE PERMITS PERMIT 20204

AIR NEW SOURCE PERMITS REGISTRATION 22977

AIR NEW SOURCE PERMITS REGISTRATION 24252

AIR NEW SOURCE PERMITS REGISTRATION 26158

AIR NEW SOURCE PERMITS REGISTRATION 26410

AIR NEW SOURCE PERMITS REGISTRATION 32733

AIR NEW SOURCE PERMITS REGISTRATION 37488

AIR NEW SOURCE PERMITS REGISTRATION 42054

AIR NEW SOURCE PERMITS REGISTRATION 46790

AIR NEW SOURCE PERMITS ACCOUNT NUMBER OC00073

AIR NEW SOURCE PERMITS REGISTRATION 75999

AIR NEW SOURCE PERMITS AFS NUM 4836100002

AIR NEW SOURCE PERMITS REGISTRATION 70650

AIR NEW SOURCE PERMITS REGISTRATION 71338 AIR NEW SOURCE PERMITS REGISTRATION 53324

AIR NEW SOURCE PERMITS REGISTRATION 71829

AIR NEW SOURCE PERMITS REGISTRATION 53572

AIR NEW SOURCE PERMITS REGISTRATION 73921

AIR NEW SOURCE PERMITS REGISTRATION 73779

AIR NEW SOURCE PERMITS REGISTRATION 76955 AIR NEW SOURCE PERMITS REGISTRATION 76726

AIR NEW SOURCE PERMITS REGISTRATION 78770

AIR NEW SOURCE PERMITS REGISTRATION 78820 AIR NEW SOURCE PERMITS REGISTRATION 78445 AIR NEW SOURCE PERMITS REGISTRATION 80163 AIR NEW SOURCE PERMITS REGISTRATION 79817 AIR NEW SOURCE PERMITS REGISTRATION 80740 AIR NEW SOURCE PERMITS REGISTRATION 80739 AIR NEW SOURCE PERMITS REGISTRATION 80736 AIR NEW SOURCE PERMITS REGISTRATION 80930 AIR NEW SOURCE PERMITS REGISTRATION 80705 AIR NEW SOURCE PERMITS REGISTRATION 80707 AIR NEW SOURCE PERMITS REGISTRATION 80743 AIR NEW SOURCE PERMITS REGISTRATION 81411 AIR NEW SOURCE PERMITS REGISTRATION 81430 AIR NEW SOURCE PERMITS REGISTRATION 81828 AIR NEW SOURCE PERMITS REGISTRATION 82031 AIR NEW SOURCE PERMITS REGISTRATION 84794 AIR NEW SOURCE PERMITS REGISTRATION 90758 AIR NEW SOURCE PERMITS REGISTRATION 84928 AIR NEW SOURCE PERMITS REGISTRATION 90117 AIR NEW SOURCE PERMITS REGISTRATION 91404 AIR NEW SOURCE PERMITS REGISTRATION 91433 AIR NEW SOURCE PERMITS REGISTRATION 93700 AIR NEW SOURCE PERMITS REGISTRATION 95774 AIR NEW SOURCE PERMITS REGISTRATION 98962 AIR NEW SOURCE PERMITS REGISTRATION 100489 AIR NEW SOURCE PERMITS REGISTRATION 100124 AIR NEW SOURCE PERMITS REGISTRATION 101051 AIR NEW SOURCE PERMITS REGISTRATION 99542 AIR NEW SOURCE PERMITS REGISTRATION 101075 AIR NEW SOURCE PERMITS REGISTRATION 101065 AIR NEW SOURCE PERMITS REGISTRATION 97864 AIR NEW SOURCE PERMITS REGISTRATION 98907 AIR NEW SOURCE PERMITS REGISTRATION 98665 AIR NEW SOURCE PERMITS REGISTRATION 98937 AIR NEW SOURCE PERMITS REGISTRATION 104095 AIR NEW SOURCE PERMITS REGISTRATION 104083 AIR NEW SOURCE PERMITS REGISTRATION 101938 AIR NEW SOURCE PERMITS REGISTRATION 104054 AIR NEW SOURCE PERMITS REGISTRATION 104059 AIR NEW SOURCE PERMITS REGISTRATION 102344 AIR NEW SOURCE PERMITS REGISTRATION 102561 AIR NEW SOURCE PERMITS REGISTRATION 104052 AIR NEW SOURCE PERMITS REGISTRATION 104723 AIR NEW SOURCE PERMITS REGISTRATION 104057 AIR NEW SOURCE PERMITS REGISTRATION 110513 AIR NEW SOURCE PERMITS REGISTRATION 113437 AIR NEW SOURCE PERMITS REGISTRATION 108759 AIR NEW SOURCE PERMITS REGISTRATION 107032 AIR NEW SOURCE PERMITS REGISTRATION 107487 AIR NEW SOURCE PERMITS REGISTRATION 107832 AIR NEW SOURCE PERMITS REGISTRATION 114657 AIR NEW SOURCE PERMITS REGISTRATION 106680 AIR NEW SOURCE PERMITS REGISTRATION 106821 AIR NEW SOURCE PERMITS REGISTRATION 116840 AIR NEW SOURCE PERMITS REGISTRATION 115226 AIR NEW SOURCE PERMITS REGISTRATION 107580 AIR NEW SOURCE PERMITS REGISTRATION 111631 PUBLIC WATER SYSTEM/SUPPLY REGISTRATION 1810114 **WATER RIGHTS ID NUMBER 4664**

AIR NEW SOURCE PERMITS REGISTRATION 79048 AIR NEW SOURCE PERMITS REGISTRATION 79512 AIR NEW SOURCE PERMITS REGISTRATION 80331 AIR NEW SOURCE PERMITS REGISTRATION 80113 AIR NEW SOURCE PERMITS REGISTRATION 80742 AIR NEW SOURCE PERMITS REGISTRATION 80738 AIR NEW SOURCE PERMITS REGISTRATION 80712 AIR NEW SOURCE PERMITS REGISTRATION 81074 AIR NEW SOURCE PERMITS REGISTRATION 80706 AIR NEW SOURCE PERMITS REGISTRATION 80711 AIR NEW SOURCE PERMITS REGISTRATION 81410 AIR NEW SOURCE PERMITS REGISTRATION 81431 AIR NEW SOURCE PERMITS REGISTRATION 81292 AIR NEW SOURCE PERMITS REGISTRATION 81587 AIR NEW SOURCE PERMITS REGISTRATION 83760 AIR NEW SOURCE PERMITS REGISTRATION 85529 AIR NEW SOURCE PERMITS REGISTRATION 86825 AIR NEW SOURCE PERMITS REGISTRATION 91170 AIR NEW SOURCE PERMITS REGISTRATION 87511 AIR NEW SOURCE PERMITS REGISTRATION 91398 AIR NEW SOURCE PERMITS REGISTRATION 92418 AIR NEW SOURCE PERMITS REGISTRATION 95104 AIR NEW SOURCE PERMITS REGISTRATION 99037 AIR NEW SOURCE PERMITS REGISTRATION 98635 AIR NEW SOURCE PERMITS REGISTRATION 100137 AIR NEW SOURCE PERMITS REGISTRATION 101050 AIR NEW SOURCE PERMITS REGISTRATION 101160 AIR NEW SOURCE PERMITS REGISTRATION 99960 AIR NEW SOURCE PERMITS REGISTRATION 99940 AIR NEW SOURCE PERMITS REGISTRATION 101055 AIR NEW SOURCE PERMITS REGISTRATION 101137 AIR NEW SOURCE PERMITS REGISTRATION 96918 AIR NEW SOURCE PERMITS REGISTRATION 98924 AIR NEW SOURCE PERMITS REGISTRATION 101083 AIR NEW SOURCE PERMITS REGISTRATION 104097 AIR NEW SOURCE PERMITS REGISTRATION 102793 AIR NEW SOURCE PERMITS REGISTRATION 104088 AIR NEW SOURCE PERMITS REGISTRATION 102106 AIR NEW SOURCE PERMITS REGISTRATION 104086 AIR NEW SOURCE PERMITS REGISTRATION 104091 AIR NEW SOURCE PERMITS REGISTRATION 104048 AIR NEW SOURCE PERMITS REGISTRATION 104050 AIR NEW SOURCE PERMITS REGISTRATION 104090 AIR NEW SOURCE PERMITS REGISTRATION 102624 AIR NEW SOURCE PERMITS REGISTRATION 109384 AIR NEW SOURCE PERMITS REGISTRATION 108655 AIR NEW SOURCE PERMITS REGISTRATION 110188 AIR NEW SOURCE PERMITS REGISTRATION 108747 AIR NEW SOURCE PERMITS REGISTRATION 106067 AIR NEW SOURCE PERMITS REGISTRATION 107933 AIR NEW SOURCE PERMITS REGISTRATION 106268 AIR NEW SOURCE PERMITS REGISTRATION 114763 AIR NEW SOURCE PERMITS REGISTRATION 108569 AIR NEW SOURCE PERMITS REGISTRATION 106740 AIR NEW SOURCE PERMITS REGISTRATION 115102 AIR NEW SOURCE PERMITS REGISTRATION 115609 AIR NEW SOURCE PERMITS REGISTRATION 108092 STORMWATER PERMIT TXR05L392

WASTEWATER PERMIT WQ0000475000

WASTEWATER EPA ID TX0006327

AIR EMISSIONS INVENTORY ACCOUNT NUMBER OC0007

Compliance History Period: September 01, 2008 to August 31, 2013 Rating Year: 2013 Rating Date: 09/01/2013

Date Compliance History Report Prepared: March 05, 2014

Agency Decision Requiring Compliance History: Enforcement

Component Period Selected: March 05, 2009 to March 05, 2014

TCEQ Staff Member to Contact for Additional Information Regarding This Compliance History.

Name: Farhaud Abbaszadeh Phone: (512) 239-0779

Site and Owner/Operator History:

1) Has the site been in existence and/or operation for the full five year compliance period? YES

2) Has there been a (known) change in ownership/operator of the site during the compliance period? NO

3) If **YES** for #2, who is the current owner/operator? N/A

4) If **YES** for #2, who was/were the prior N/A

owner(s)/operator(s)?

5) If **YES**, when did the change(s) in owner or operator N/A

Components (Multimedia) for the Site Are Listed in Sections A - J

A. Final Orders, court judgments, and consent decrees:

1 Effective Date: 04/20/2009 ADMINORDER 2008-1315-IWD-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 2D TWC Chapter 26, SubChapter A 26.121(a)

30 TAC Chapter 305, SubChapter F 305.125(1)

Rgmt Prov: Effluent Limits PERMIT

Description: Failure to comply with permit effluent limits as documented by a TCEQ record review of self-reported data.

2 Effective Date: 05/18/2009 ADMINORDER 2008-0971-AIR-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov:914, Special Condition 1 PERMIT

O-02074, General Terms and Conditions OP

O-02074, Special Condition 15 OP

Description: Failure to maintain an emission rate below the allowable emission limit. Incident 102860.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rgmt Prov:9176, Special Condition 1 PERMIT

O-02001, General Terms and Conditions OP

O-02001, Special Condition 8 OP

Description: Failure to maintain an emission rate below the allowable emission limit. Incident 103221.

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(1)(B)

5C THSC Chapter 382 382.085(b)

Rqmt Prov: General Terms and Conditions OP

Special Condition 1 OP

Special Condition 8 PERMIT

Description: Failure to notify the agency within 24 hours of the discovery of an emissions event. Specifically, the reportable event report for the February 2, 2008, emissions event was not submitted 24 hours after the discovery of the event.

3 Effective Date: 06/01/2009 ADMINORDER 2008-1923-PWS-E (Findings Order-Agreed Order Without Denial)

Classification: Minor

Citation: 30 TAC Chapter 290, SubChapter D 290.42(d)(2)(E)

Description: Failed to provide an air gap connection to waste for the FTW connection at the Facility.

Classification: Minor

Citation: 30 TAC Chapter 290, SubChapter D 290.42(d)(13)

Description: Failed to identify the chlorine dioxide line every five feet either by the use of a label or by various colors of

paint.

Classification: Minor

Citation: 30 TAC Chapter 290, SubChapter D 290.41(e)(2)(C)

Description: Failed to post a sign at the raw water intakes warning that a restricted zone has been established and that all

recreational activities and trespassing is prohibited within the area.

Classification: Moderate

Citation: 30 TAC Chapter 290, SubChapter D 290.44(h)(1)(A)

Description: Failed to install a backflow prevention assembly or an air gap at all locations where an actual or potential

contamination hazard exist.

Classification: Minor

Citation: 30 TAC Chapter 290, SubChapter D 290.42(e)(3)(A)

Description: Failed to provide disinfection equipment with a capacity of at least 50% greater than the highest expected

disinfectant dosage. Classification: Minor

Citation: 30 TAC Chapter 290, SubChapter D 290.42(I)

Description: Failed to maintain an up-to-date plant operations manual for operator review and reference.

Classification: Minor

Citation: 30 TAC Chapter 290, SubChapter D 290.43(c)(8)

Description: Failed to maintain the Facility's clearwell in strict accordance with current AWWA standards.

Classification: Moderate

Citation: 30 TAC Chapter 290, SubChapter F 290.110(b)(4)

5A THSC Chapter 341, SubChapter A 341.0315(c)

Description: Failed to maintain the residual disinfectant concentration in the water of at least 0.2 milligrams per liter

("mg/L") free chlorine throughout the distribution system at all times.

Classification: Minor

Citation: 30 TAC Chapter 290, SubChapter D 290.46(n)(2)

Description: Failed to provide an up-to-date map of the distribution system.

Classification: Minor

Citation: 30 TAC Chapter 290, SubChapter D 290.42(d)(2)(D)

Description: Failed to properly locate the filter so that common walls do not exist between the filter and aerators, mixing,

and sedimentation basins or clearwells.

4 Effective Date: 06/15/2009 ADMINORDER 2008-1817-AIR-E (1660 Order-Agreed Order With Denial)

Classification: Major

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rgmt Prov: General Terms and Conditions OP

Special Condition 1 PERMIT
Special Condition 8 OP

Description: Failure to maintain an emission rate below the allowable emission limits.

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(1)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Ramt Prov: Special Condition 2F OP

Description: Failure to submit an initial report within 24 hours for TCEQ Incident No. 110539.

5 Effective Date: 07/09/2009 ADMINORDER 2008-1167-AIR-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

```
Rgmt Prov: NSR Permit No. 9629, SC 12 PERMIT
          O-02331 General Terms and Conditions OP
          O-02331 Special Condition 6 OP
Description: Failed to operate the Cogeneration Train, emission point number ("EPN"") PG-14, at or below the nitrogen
oxide ("NOx") concentration limit of 96 parts per million ("ppm") four times between September 25 and November 11,
2006.
Classification: Moderate
          30 TAC Chapter 101, SubChapter A 101.20(1)
          30 TAC Chapter 116, SubChapter B 116.115(c)
          30 TAC Chapter 117, SubChapter B 117.140(c)(1)
          30 TAC Chapter 117, SubChapter B 117.140(e)
          30 TAC Chapter 117, SubChapter B 117.340(c)(1)
          30 TAC Chapter 117, SubChapter B 117.340(f)(1)
          30 TAC Chapter 117, SubChapter G 117.8100(a)(1)(B)(i)
          30 TAC Chapter 122, SubChapter B 122.143(4)
          40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.8
          40 CFR Chapter 60, SubChapter C, PT 60, SubPT Db 60.46b(f)(1)
          40 CFR Chapter 60, SubChapter C, PT 60, SubPT Db 60.48b(b)(1)
          5C THSC Chapter 382 382.085(b)
Rgmt Prov:9629 Special Condition 3 PERMIT
          O-02331 General Terms and Conditions OP
          O-02331 Special Condition 1A OP
          O-02331 Special Condition 1D OP
          O-02331 Special Condition 4B OP
          O-02331 Special Condition 4F OP
          O-02331 Special Condition 6 OP
Description: Failed to conduct a Relative Accuracy Test ("RAT") and a 7-day Calibration Drift ("CD") test on a NOx
analyzer in the Cogeneration Unit, which resulted in the inability to certify that the continuous emissions monitoring system
("CEMS") was operating properly.
Classification: Moderate
          30 TAC Chapter 101, SubChapter A 101.20(1)
          30 TAC Chapter 116, SubChapter B 116.115(c)
          30 TAC Chapter 117, SubChapter B 117.140(d)
          30 TAC Chapter 117, SubChapter B 117.140(e)
          30 TAC Chapter 117, SubChapter B 117.340(e)
          30 TAC Chapter 117, SubChapter B 117.340(f)(1)
          30 TAC Chapter 117, SubChapter G 117.8100(a)(1)(B)(iii)
          30 TAC Chapter 117, SubChapter G 117.8120(1)(A)
          30 TAC Chapter 122, SubChapter B 122.143(4)
          40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.13
          40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.8
           40 CFR Chapter 60, SubChapter C, PT 60, SubPT Db 60.46b(c)
          40 CFR Chapter 60, SubChapter C, PT 60, SubPT Db 60.46b(f)(1)
          5C THSC Chapter 382 382.085(b)
Rgmt Prov: 9629 Special Condition 3 PERMIT
          O-02331 General Terms and Conditions OP
          O-02331 Special Condition 1A OP
          O-02331 Special Condition 1D OP
          O-02331 Special Condition 4B OP
          O-02331 Special Condition 4F OP
          O-02331 Special Condition 6 OP
Description: Failed to conduct a RAT and a 7-day CD test on a carbon monoxide ("CO") analyzer in the Cogeneration Unit,
which resulted in the inability to certify that the CEMS was operating properly.
Classification: Moderate
          30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)
          30 TAC Chapter 122, SubChapter B 122.143(4)
          5C THSC Chapter 382 382.085(b)
Rqmt Prov:9176, Special Condition 1 PERMIT
          O-02001, General Terms and Conditions OP
```

Description: Failed to prevent unauthorized emissions.

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.211(b)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov: O-02001 General Terms and Conditions OP

O-02001 Special Condition 2G OP

Description: Failed to submit a final record for an emissions event (Incident No. 105482) within two weeks after the end of the event The initial report was submitted timely, but the emissions amounts and duration subsequently changed, and a final record with the corrected information was not submitted by April 17, 2008 (two weeks after the event that ended on April 3, 2008). On June 1, 2008, the correct amount and duration of emissions was submitted via electronic mail.

6 Effective Date: 10/04/2009 ADMINORDER 2009-0285-AIR-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rgmt Prov: General Terms and Conditions OP

Special Condition 1 PERMIT Special Condition 15 OP

Description: Failure to maintain an emission rate below the allowable emission limits.

Classification: Moderate

30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rgmt Prov: General Terms and Conditions OP

Special Condition 1 PERMIT Special Condition 8 OP

Description: Failure to maintain an emission rate below the allowable emission limits.

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(1)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov: O-02001 Special Condition 2F OP

Description: Failure to submit an initial report within 24 hours for T CEQ Incident No. 116375.

7 Effective Date: 10/31/2009 ADMINORDER 2009-0600-AIR-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rgmt Prov: 20204, Special Condition 1 PERMIT

O-02055, General Terms and Conditions OP

O-02055, Special Condition 8 OP

Description: Failure to maintain an emission rate below the allowable emission limits.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Ramt Prov: 20204 Special Condition 1 PERMIT

FOP O-02055 General Terms and Conditions OP

FOP O-02055 Special Condition 8 OP

Description: Failure to maintain an emission rate below the allowable emission limits.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

Rgmt Prov:914, Special Condition 1 PERMIT

O-02074, General Terms and Conditions OP

O-02074, Special Condition 15 OP

Description: Failure to maintain an emission rate below the allowable emission limits.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rgmt Prov:914, Special Condition 1 PERMIT

O-02074, General Terms and Conditions OP

O-02074, Special Condition 15 OP

Description: Failure to maintain an emission rate below the allowable emission limits.

8 Effective Date: 02/07/2010 ADMINORDER 2009-1011-AIR-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rgmt Prov: General Terms and Conditions OP

Special Condition 1 PERMIT Special Condition 8 OP

Description: Failure to maintain an emission rate below the allowable emission limits (Incident 121831). Specifically, the emissions event was caused by the Suction Separator, Purge Compressor 1st, 2nd, 3rd, and 4th Stage Blowdowns, and Wax Tank Vent being left open to atmosphere during a maintenance activity on the C Unit Flare Header Guard Valve.

Effective Date: 07/11/2010 ADMINORDER 2009-1958-AIR-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rgmt Prov: General Terms and Conditions OP

Special Condition 1 PERMIT Special Condition 15 OP

Description: Failure to maintain an emission rate below the allowable emission limits.

Classification: Moderate

30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov: General Terms and Conditions OP

Special Condition 1 PERMIT Special Condition 15 OP

Description: Failure to maintain an emission rate below the allowable emission limits.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov: General Terms and Conditions OP

Special Condition 1 PERMIT Special Condition 8 OP

Description: Failure to maintain an emission rate below the allowable emission limits.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4) 5C THSC Chapter 382 382.085(b)

Rqmt Prov: GENERAL CONDITIONS OP

SC 1 PERMIT SC 8 OP

Description: Failure to maintain an emission rate below the allowable emission limits.

10 Effective Date: 03/19/2011 ADMINORDE

ADMINORDER 2010-0839-MLM-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov: GENERAL CONDITIONS OP

SC 1 PERMIT SC 8 OP

Description: Failure to maintain an emission rate below the allowable emission limits.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4) 30 TAC Chapter 335, SubChapter H 335.221(a)(15)

40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.104(b)

5C THSC Chapter 382 382.085(b)

Rqmt Prov:Condition X(B)(1)(j) PERMIT

SC 17 OP SC 1A OP

Description: Failure to comply with the carbon monoxide emission limit of 14.6 lb/hr at the Incinerator as reported in the deviation reports for September 1, 2008, until February 28, 2009, and March 1, 2009, until August 31, 2009.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rgmt Prov:GENERAL TERMS AND CONDITIONS OP

SC 1 PERMIT

SC 8 OP

Description: Failure to maintain an emission rate below the allowable emission limits.

11 Effective Date: 08/13/2011

ADMINORDER 2011-0208-AIR-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov:SC 1 PERMIT

SC 1A OP

Description: Failure to maintain an emission rate below the allowable emission limits for Incident 146789.

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(c)

5C THSC Chapter 382 382.085(b)

Description: Failure to satisfy the final reporting requirements for a reportable emissions event for Incident 145301.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov:SC 1 PERMIT

SC 1A OP

Description: Failure to maintain an emission rate below the allowable emission limit for Incident 145301.

12 Effective Date: 05/25/2012 ADMINORDER 2011-1732-AIR-E (1660 Order-Agreed Order With Denial)

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.211(b)

5C THSC Chapter 382 382.085(b)

Description: Failed to timely submit the final record for a maintenance activity (Incident No. 155487). Specifically, the maintenance activity began on June 10, 2011 and ended on June 11, 2011, and the final record was submitted on July 19, 2011, more than two weeks after the end of the maintenance activity

Classification: Moderate

Citation: 30 TAC Ch

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov:SC 1 PERMIT SC 1A OP

Description: Failed to prevent unauthorized emissions during a maintenance activity (Incident No. 155487). Specifically, during a scheduled maintenance activity that began on June 10, 2011, and lasted approximately 16 hours and 20 minutes, the Respondent released approximately 4,024.75 pounds ("lbs") of volatile organic compounds and 4,958.96 lbs of particulate matter from the Regenerative Thermal Oxidizer's Baghouse Vent [Emission Point No. PL-10] located in the D Unit.

13 Effective Date: 04/07/2013 ADMINORDER 2012-1198-IWD-E (Findings Order-Agreed Order Without Denial)

Classification: Moderate

Citation: 2D TWC Chapter 26, SubChapter A 26.121(a)

30 TAC Chapter 305, SubChapter F 305.125(1)

Ramt Prov: Effluent Limits PERMIT

Description: Failure to comply with permit effluent limits as documented by a TCEQ record review of self-reported data.

14 Effective Date: 04/27/2013 ADMINORDER 2012-0624-AIR-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rgmt Prov: GENERAL TERMS AND CONDITIONS OP

SC 1 PERMIT SC 8 OP

Description: Failed to prevent unauthorized emissions.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rgmt Prov: GENERAL TERMS AND CONDITIONS OP

SC 1 PERMIT

SC 8 OP

Description: Failed to prevent unauthorized emissions.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rgmt Prov:GENERAL TERMS AND CONDITIONS OP

SC 1 PERMIT

SC 8 OP

Description: Failed to prevent unauthorized emissions.

15 Effective Date: 06/03/2013 ADMINORDER 2012-2344-AIR-E (1660 Order-Agreed Order With Denial)

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Ramt Prov:SC 1 PERMIT

Description: Failure to maintain an emission rate below the allowable emission limits for Incident 169473.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b)

Rqmt Prov:SC 1 PERMIT

SC 11 OP

Description: Failure to maintain an emission rate below the allowable emission limits for Incident 172088.

B. Criminal convictions:

N/A

C. Chronic excessive emissions events:

N/A

D. The approval dates of investigations (CCEDS Inv. Track. No.):

Item 1	March 23, 2009	(737577)
Item 2	March 25, 2009	(724903)
Item 3	April 23, 2009	(750319)
Item 4	May 11, 2009	(741609)
Item 5	May 22, 2009	(768403)
Item 6	June 04, 2009	(744517)
Item 7	June 14, 2009	(768404)
Item 8	July 23, 2009	(762808)
Item 9	July 28, 2009	(804796)
Item 10	August 24, 2009	(804795)
Item 11	September 10, 2009	(762825)
Item 12	September 11, 2009	(767515)
Item 13	September 15, 2009	(775525)
Item 14	September 24, 2009	(764051)
Item 15	October 01, 2009	(764835)
Item 16	October 05, 2009	(764127)
Item 17	October 14, 2009	(767507)
Item 18	October 23, 2009	(804797)
Item 19	November 03, 2009	(780849)
Item 20	November 23, 2009	(804798)
Item 21	November 24, 2009	(781552)
Item 22	December 09, 2009	(784937)
Item 23	January 11, 2010	(804799)
Item 24	January 22, 2010	(804800)
Item 25	January 28, 2010	(785297)
Item 26	February 01, 2010	(788600)
Item 27	February 16, 2010	(791368)
Item 28	February 25, 2010	(804793)
Item 29	March 22, 2010	(793111)
Item 30	April 20, 2010	(830933)
Item 31	May 20, 2010	(830934)
Item 32	May 26, 2010	(802185)
Item 33	June 03, 2010	(802860)
Item 34	June 10, 2010	(802838)
Item 35	June 21, 2010	(846284)
Item 36	July 21, 2010	(860879)
Item 37	July 31, 2010	(826906)
Item 38	August 20, 2010	(866847)
Item 39	September 16, 2010	(864081)
Item 40	September 22, 2010	(873917)
Item 41	October 04, 2010	(865152)

Item 42	October 20, 2010	(881518)
Item 43	November 18, 2010	(888044)
Item 44	November 29, 2010	(877136)
Item 45	December 15, 2010	(896259)
Item 46	January 19, 2011	(891097)
Item 47	January 20, 2011	(902320)
Item 48	January 21, 2011	(887844)
Item 49	February 03, 2011	(893116)
Item 50	February 15, 2011	(909102)
Item 51	February 23, 2011	(899236)
Item 52	March 16, 2011	(916357)
Item 53	April 11, 2011	(924832)
Item 54	April 18, 2011	(912901)
Item 55	May 11, 2011	(912705)
Item 56	May 18, 2011	(938043)
Item 57	May 31, 2011	(915887)
Item 58	June 14, 2011	(945411)
Item 59	July 13, 2011	(952639)
Item 60	July 19, 2011	(922140)
Item 61	August 16, 2011	(959321)
Item 62	September 16, 2011	(965354)
Item 63	September 22, 2011	(956748)
Item 64	October 17, 2011	(971394)
Item 65	October 26, 2011	(962475)
Item 66	November 17, 2011	(977553)
Item 67	November 29, 2011	(958427)
Item 68	December 13, 2011	(984321)
Item 69	January 31, 2012	(981940)
Item 70	February 19, 2012	(987680)
Item 71	May 25, 2012	(1006347)
Item 72	June 15, 2012	(1013697)
Item 73	June 23, 2012	(1024186)
Item 74	July 06, 2012	(1014731)
Item 75	August 22, 2012	(1037956)
Item 76	October 16, 2012	(1060922)
Item 77	November 16, 2012	(1060923)
Item 78	December 13, 2012	(1060924)
Item 79	January 17, 2013	(1078996)
Item 80 Item 81	January 24, 2013	(1053366) (1078995)
Item 82	February 18, 2013 March 14, 2013	(1078933)
Item 83	April 17, 2013	(1089322)
Item 84	May 16, 2013	(1106641)
Item 85	May 21, 2013	(1100041)
Item 86	May 24, 2013	(1093717)
Item 87	June 11, 2013	(1110317)
Item 88	June 27, 2013	(1110317)
Item 89	July 23, 2013	(1117201)
Item 90	August 19, 2013	(1117201)
Item 91	September 19, 2013	(1124957)
Item 92	October 22, 2013	(1125337)
Item 93	November 17, 2013	(1133287)
Item 94	November 17, 2013 November 27, 2013	(1140000)
Item 95	December 03, 2013	(1133073)
Item 96	December 11, 2013	(1147145)
accini Ju	December 11, 2013	(LF1 (1 +4)

E. Written notices of violations (NOV) (CCEDS Inv. Track. No.):

A notice of violation represents a written allegation of a violation of a specific regulatory requirement from the commission to a

regulated entity. A notice of violation is not a final enforcement action, nor proof that a violation has actually occurred. 1 Date: 08/13/2013 (1101129) CN600128284 Self Report? Classification: Moderate 30 TAC Chapter 115, SubChapter D 115.352(4) Citation: 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4) 40 CFR Chapter 63, SubChapter C, PT 63, SubPT FFFF 63.2480(a) 40 CFR Chapter 63, SubChapter C, PT 63, SubPT UU 63.1033(b)(1) Special Condition 4E PERMIT Special Term & Condition 11 OP Special Term & Condition 1A OP Description: Failure to prevent open-ended lines. (C10)NO Self Report? Classification: Moderate Citation: 30 TAC Chapter 116, SubChapter B 116.116(b)(1) 30 TAC Chapter 122, SubChapter B 122.143(4) 5C THSC Chapter 382 382.085(b) GENERAL TERMS AND CONDITIONS OP Description: Failure to maintain the representations of NSR Permit 9176. (Category B19(g)(1) Date: 08/30/2013 (1072932) CN600128284 Self Report? NO Classification: Moderate 30 TAC Chapter 116, SubChapter B 116.115(c) Citation: 30 TAC Chapter 122, SubChapter B 122.143(4) 5C THSC Chapter 382 382.085(b) Special Conditions, 16 PERMIT Special Terms and Conditions, 11A OP Failure to demonstrate seal intergity of the floating roof for the Number 1 Vinly Description: Acetate (VA) tank. Self Report? Classification: Moderate 30 TAC Chapter 116, SubChapter B 116.115(c) Citation: 30 TAC Chapter 122, SubChapter B 122.143(4) 40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(3)(ii) 5C THSC Chapter 382 382.085(b) Special Condition, 6A PERMIT Special Term & Condition 11A OP Special Term & Condition 1A OP Description: Failure to maintain the CDG Flare one-hour average BTU value at or above 300 Btu/scf. Self Report? NO Classification: Moderate Citation: 30 TAC Chapter 115, SubChapter D 115.352(4) 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4) 40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-6(a)(2) 40 CFR Chapter 63, SubChapter C, PT 63, SubPT FFFF 63.2480(a) 40 CFR Chapter 63, SubChapter C, PT 63, SubPT UU 63.1033(b)(1) 5C THSC Chapter 382 382.085(b) Special Condition 4 PERMIT Special Term & Condition 1A OP Special Term and Condition, 11A OP Special Terms and Conditions, 3E PERMIT Description: Failure to prevent open-ended lines. Self Report? NO Classification: Moderate 30 TAC Chapter 115, SubChapter D 115.354(4) Citation: 30 TAC Chapter 122, SubChapter B 122.143(4) 5C THSC Chapter 382 382.085(b) Special Term and Condition, 1A OP Description: Failure to monitor pressure relief valve #3 within 24 hours of release. Self Report? Classification: Moderate Citation: 30 TAC Chapter 101, SubChapter A 101.20(3) 30 TAC Chapter 106, SubChapter A 106.6(a) 30 TAC Chapter 115, SubChapter D 115.354(2) 30 TAC Chapter 115, SubChapter D 115.354(3) 30 TAC Chapter 116, SubChapter B 116.110(a)

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-1(a) 40 CFR Chapter 63, SubChapter C, PT 63, SubPT FFFF 63.2480 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.181 40 CFR Chapter 63, SubChapter C, PT 63, SubPT UU 63.1023(a) 5C THSC Chapter 382 382.085(b) Special Condition, 3C PERMIT Special Condition, 3E PERMIT Special Condition, 3F PERMIT Special Condition, 3G PERMIT Special Condition, 4 PERMIT Special Term & Condition 1A OP Special Term and Condition, 11 OP Failure to monitor Leak Detection and Repair (LDAR) components. Moderate Classification: 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 116, SubChapter B 116.116(b)(1) 30 TAC Chapter 122, SubChapter B 122.143(4) 5C THSC Chapter 382 382.085(b) General Condition 1 PERMIT Special Term and Condition, 11 OP Failure to maintain representation of NSR Permit 20204. Classification: Moderate 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(E) 30 TAC Chapter 116, SubChapter B 116.115(c) 5C THSC Chapter 382 382.085(b) General Condition 7 PERMIT Special Terms and Conditions, 11A OP Failure to provide records of emission rates. 11/22/2013 (1123054) CN600128284 Self Report? Classification: Minor 30 TAC Chapter 335, SubChapter F 335.152(a)(1) 40 CFR Chapter 264, SubChapter I, PT 264, SubPT C 264.15(d) P.P.II.C.1.k. PERMIT P.P.II.C.2.a. PERMIT Failure to properly complete the permitted daily tank inspection with the inspector's full name. Classification: Minor 30 TAC Chapter 335, SubChapter E 335.112 40 CFR Chapter 265, SubChapter I, PT 265, SubPT B 265.15(d) Failure to properly complete the less than 90 days daily tank inspections with the inspector's full name. Classification: Major 30 TAC Chapter 335, SubChapter F 335.152(a)(2) 40 CFR Chapter 264, SubChapter I, PT 264, SubPT C 264.35 P.P.II.C.1.k. PERMIT P.P.II.C.2.b PERMIT Failure to provide adequate aisle space between two hazardous waste tractor trailers. Self Report? NO Classification: Major 30 TAC Chapter 327 327.5 40 CFR Chapter 265, SubChapter I, PT 265, SubPT D 265.51(b) Failure to immediately respond to a release of hazardous waste located at G-Unit Central Hazardous Waste Tank (NOR 205). 01/24/2014 (1128705) CN600128284 Self Report? NO Classification: Moderate 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4) 40 CFR Chapter 61, SubChapter C, PT 61, SubPT FF 61.354(a)(2) Special Terms and Conditions, 15 OP Special Terms and Conditions, 15, H PERMIT Special Terms and Conditions, 1A OP Failure to monitor carbon beds Classification: Moderate 30 TAC Chapter 116, SubChapter B 116.115(c)

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)

Description:

Self Report?

Description:

Self Report?

Description:

Date:

Citation:

Description:

Self Report?

Description:

Self Report?

Description:

Description:

Citation:

Date:

Citation:

Description: Self Report?

Citation:

Citation:

3

Citation:

Citation:

40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1206(b)(1) 40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1206(b)(5)

5C THSC Chapter 382 382.085(b) Special Terms and Conditions 15 OP Special Terms and Conditions 15K PERMIT Special Terms and Conditions 1A OP

Description: Failure to maintain the incinerator's kiln above 1255 degrees fahrenheit as

established during comprehensive performance testing (CPT) and listed in the

Notification of Compliance (NOC).

Self Report?

Classification:

Moderate

Citation:

30 TAC Chapter 116, SubChapter B 116.116(a)(1) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) Special Terms and Conditions, 15 OP

Description: Failure to adhere to permit representations

Self Report?

NO

Classification:

Moderate

30 TAC Chapter 116, SubChapter B 116.115(c) Citation:

30 TAC Chapter 122, SubChapter B 122.143(4)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1203(a)(5)(i) 40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1209(a)(1) 40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1209(a)(2) 40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1209(d)(2)

5C THSC Chapter 382 382.085(b) Special Terms 21(B)(1) PERMIT Special Terms and Condition 1A OP Special Terms and Conditions 15 OP

Description: Failure to follow proper Continous Emission Montoring (CEMS) equipment

calibration procedures

Self Report?

Classification:

Classification:

Moderate

Citation:

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) Special Terms and Conditions, 1A OP

Special Terms and Conditions, 20D PERMIT

Description: Failure to maintain proper scrubber pH as required by Hazardous Waste Permit

No. 50230, TableV.H.2.

Date:

02/04/2014 (1144948)

NO

CN600128284

Moderate

Self Report? Citation:

Self Report?

Citation:

30 TAC Chapter 116, SubChapter B 116.116(b)(1) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) General Condition 1 PERMIT Special term & Condition 11 OP

Description: Failure to maintain production rates. (Category B19g1)

30 TAC Chapter 122, SubChapter B 122.143(4)

30 TAC Chapter 122, SubChapter B 122.145(2)(A)

5C THSC Chapter 382 382.085(b) General Terms and Conditions OP

Description: Failure to report a deviation on the previous Semi-Annual Deviation Report.

(Category B3)

Self Report? NO Classification:

Classification:

Moderate

Moderate

Citation:

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(3)(ii)

5C THSC Chapter 382 382.085(b) Special Condition 6A PERMIT Special Term & Condition 11 OP

Description: Failure to ensure the CDG Flare British Thermal Units (BTUs) value was

maintained. (Category B19g1)

Self Report? NO Classification:

Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-6(a)(2) 40 CFR Chapter 63, SubChapter C, PT 63, SubPT FFFF 63.2480(a) 40 CFR Chapter 63, SubChapter C, PT 63, SubPT UU 63.1033(b)(1)

5C THSC Chapter 382 382.085(b) Special Condition 3(E) PERMIT Special Condition 4 PÉRMIT Special Term & Condition 11 OP Special Term & Condition 1A OP

Failure to maintain a sealing device on an open-ended line. (Category C10) Description: Self Report? Classification: Moderate

5

Citation:

30 TAC Chapter 116, SubChapter B 116.116(b)(1) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) General Condition 1 PERMIT Special Term & Condition 11 OP

Description:

Failure to maintain yearly production rates in the Isobutyl Acrylate (IBA) unit.

(Category B19g1)

Self Report?

Classification:

Moderate

Citation:

30 TAC Chapter 115, SubChapter D 115.354(4) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) Special Term & Condition 1A OP

Description:

Failure to monitor the relief valve wihtin 24 hours of release. (Category C7)

Self Report?

NO

Classification:

Moderate

Citation:

30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THSC Chapter 382 382.085(b) Special Condition 13 PERMIT Special Term & Condition 11 OP

Description:

Failure to maintain the Regenerative Thermal Oxidizer (RTO) temperature.

(Category B19g1)

F. Environmental audits:

N/A

G. Type of environmental management systems (EMSs):

N/A

H. Voluntary on-site compliance assessment dates:

N/A

I. Participation in a voluntary pollution reduction program:

J. Early compliance:

N/A

Sites Outside of Texas:

N/A

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY



IN THE MATTER OF AN	Š	BEFORE THE
ENFORCEMENT ACTION	§	
CONCERNING	§	TEXAS COMMISSION ON
E. I. DU PONT DE NEMOURS AND	§	TEXAS COMMISSION ON
COMPANY	§	
RN100542711	§	ENVIRONMENTAL QUALITY

AGREED ORDER DOCKET NO. 2014-0377-AIR-E

At its ______ agenda, the Texas Commission on Environmental Quality ("the Commission" or "TCEQ") considered this agreement of the parties, resolving an enforcement action regarding E. I. du Pont de Nemours and Company ("Respondent") under the authority of Tex. Health & Safety Code ch. 382 and Tex. Water Code ch. 7. The Executive Director of the TCEQ, through the Enforcement Division, and the Respondent presented this agreement to the Commission.

The Respondent understands that it has certain procedural rights at certain points in the enforcement process, including, but not limited to, the right to formal notice of violations, notice of an evidentiary hearing, the right to an evidentiary hearing, and a right to appeal. By entering into this Agreed Order, the Respondent agrees to waive all notice and procedural rights.

It is further understood and agreed that this Order represents the complete and fully-integrated settlement of the parties. The provisions of this Agreed Order are deemed severable and, if a court of competent jurisdiction or other appropriate authority deems any provision of this Agreed Order unenforceable, the remaining provisions shall be valid and enforceable. The duties and responsibilities imposed by this Agreed Order are binding upon the Respondent.

The Commission makes the following Findings of Fact and Conclusions of Law:

I. FINDINGS OF FACT

1. The Respondent owns and operates a chemical manufacturing plant at 3055 Farm-to-Market Road 1006 in Orange, Orange County, Texas (the "Plant").

- 2. The Plant consists of one or more sources as defined in Tex. Health & Safety Code § 382.003(12).
- 3. During a record review conducted on February 4, 2014, TCEQ staff documented the Respondent released 14,435 pounds ("lbs") of gaseous ethylene, 1,222 lbs of propane, and 371 lbs of methacrylic acid from the Dump Valve Stacks, Emission Point Number PLUM-G, during an emissions event (Incident No. 190675) that occurred on November 12, 2013 and lasted 11 minutes. This event occurred when the sealing edge of the cone joint was not properly sealed and a torque wrench with a torque specification of 75 foot pounds was used on the valve rather than the required torque specification of 85 to 110 foot pounds which resulted in a jet fire near the Pressure Energy Recovery Process valves. The unit was shut down and the emissions from the unit were released to the atmosphere. The TCEQ determined that the emissions event could have been avoided with better operation and maintenance practices.
- 4. The Respondent received notice of the violation on March 10, 2014.

II. CONCLUSIONS OF LAW

- 1. The Respondent is subject to the jurisdiction of the TCEQ pursuant TO TEX. HEALTH & SAFETY CODE ch. 382 and TEX. WATER CODE ch. 7 and the rules of the Commission.
- 2. As evidenced by Findings of Fact No. 3, the Respondent failed to prevent unauthorized emissions, in violation of of 30 Tex. Admin. Code §§ 116.115(b)(2)(F), 116.115(c), and 122.143(4), Tex. Health & Safety Code § 382.085(b), New Source Review Permit No. 20204, Special Conditions No. 1, and Federal Operating Permit No. 02055, General Terms and Conditions and Special Terms and Conditions No. 12. Since the emissions event could have been avoided with better operation and maintenance practices, the Respondent is precluded from asserting an affirmative defense under 30 Tex. Admin. Code § 101.222.
- 3. Pursuant to Tex. Water Code § 7.051, the Commission has the authority to assess an administrative penalty against the Respondent for violations of the Texas Water Code and the Texas Health and Safety Code within the Commission's jurisdiction; for violations of rules adopted under such statutes; or for violations of orders or permits issued under such statutes.
- 4. An administrative penalty in the amount of Twenty-Five Thousand Dollars (\$25,000) is justified by the facts recited in this Agreed Order, and considered in light of the factors set forth in Tex. Water Code § 7.053. The Respondent has paid Twelve Thousand Five Hundred Dollars (\$12,500) of the administrative penalty. Twelve Thousand Five Hundred Dollars (\$12,500) shall be conditionally offset by the Respondent's completion of a Supplemental Environmental Project ("SEP").

E. I. du Pont de Nemours and Company DOCKET NO. 2014-0377-AIR-E Page 3

III. ORDERING PROVISIONS

NOW, THEREFORE, THE TEXAS COMMISSION ON ENVIRONMENTAL QUALITY ORDERS that:

1. The Respondent is assessed an administrative penalty in the amount of Twenty-Five Thousand Dollars (\$25,000) as set forth in Section II, Paragraph 4 above, for violations of TCEQ rules and state statutes. The payment of this administrative penalty and the Respondent's compliance with all the terms and conditions set forth in this Agreed Order completely resolve the violations set forth by this Agreed Order in this action. However, the Commission shall not be constrained in any manner from requiring corrective actions or penalties for other violations that are not raised here. Administrative penalty payments shall be made payable to "TCEQ" and shall be sent with the notation "Re: E. I. du Pont de Nemours and Company, Docket No. 2014-0377-AIR-E" to:

Financial Administration Division, Revenue Operations Section Attention: Cashier's Office, MC 214 Texas Commission on Environmental Quality P.O. Box 13088 Austin, Texas 78711-3088

- 2. The Respondent shall implement and complete a SEP in accordance with Tex. WATER CODE § 7.067. As set forth in Section II, Paragraph 4 above, Twelve Thousand Five Hundred Dollars (\$12,500) of the assessed administrative penalty shall be offset with the condition that the SEP defined in Attachment A, incorporated herein by reference, is implemented by the Respondent. The Respondent's obligation to pay the conditionally offset portion of the administrative penalty assessed shall be discharged upon final completion of all provisions of the SEP agreement.
- 3. The Respondent shall undertake the following technical requirements:
 - a. Within 30 days after the effective date of this Agreed Order, implement measures and/or procedures to prevent the recurrence of emissions events due to the same cause as the emissions event that occurred on November 12, 2013 (Incident No. 190675); and
 - b. Within 45 days after the effective date of this Agreed Order, submit written certification as described below, and include detailed supporting documentation including photographs, receipts, and/or other records to demonstrate compliance with Ordering Provision No. 3.a. The certification shall be notarized by a State of Texas Notary Public and include the following certification language:

"I certify under penalty of law that I have personally examined and am familiar with the information submitted and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the

information, I believe that the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fines and imprisonment for knowing violations."

The certification shall be submitted to:

Order Compliance Team Enforcement Division, MC 149A Texas Commission on Environmental Quality P.O. Box 13087 Austin, Texas 78711-3087

with a copy to:

Air Section Manager Beaumont Regional Office Texas Commission on Environmental Quality 3870 Eastex Freeway Beaumont, Texas 77703-1892

- 4. The provisions of this Agreed Order shall apply to and be binding upon the Respondent. The Respondent is ordered to give notice of the Agreed Order to personnel who maintain day-to-day control over the Plant operations referenced in this Agreed Order.
- 5. If the Respondent fails to comply with any of the Ordering Provisions in this Agreed Order within the prescribed schedules, and that failure is caused solely by an act of God, war, strike, riot, or other catastrophe, the Respondent's failure to comply is not a violation of this Agreed Order. The Respondent shall have the burden of establishing to the Executive Director's satisfaction that such an event has occurred. The Respondent shall notify the Executive Director within seven days after the Respondent becomes aware of a delaying event and shall take all reasonable measures to mitigate and minimize any delay.
- 6. The Executive Director may grant an extension of any deadline in this Agreed Order or in any plan, report, or other document submitted pursuant to this Agreed Order, upon a written and substantiated showing of good cause. All requests for extensions by the Respondent shall be made in writing to the Executive Director. Extensions are not effective until the Respondent receives written approval from the Executive Director. The determination of what constitutes good cause rests solely with the Executive Director.
- 7. The Executive Director may refer this matter to the Office of the Attorney General of the State of Texas ("OAG") for further enforcement proceedings without notice to the Respondent if the Executive Director determines that the Respondent has not complied with one or more of the terms or conditions in this Agreed Order.

E. I. du Pont de Nemours and Company DOCKET NO. 2014-0377-AIR-E Page 5

- 8. This Agreed Order shall terminate five years from its effective date or upon compliance with all the terms and conditions set forth in this Agreed Order, whichever is later.
- 9. This Agreed Order, issued by the Commission, shall not be admissible against the Respondent in a civil proceeding, unless the proceeding is brought by the OAG to: (1) enforce the terms of this Agreed Order; or (2) pursue violations of a statute within the Commission's jurisdiction, or of a rule adopted or an order or permit issued by the Commission under such a statute.
- This Agreed Order may be executed in separate and multiple counterparts, which 10. together shall constitute a single instrument. Any page of this Agreed Order may be copied, scanned, digitized, converted to electronic portable document format ("pdf"), or otherwise reproduced and may be transmitted by digital or electronic transmission, including but not limited to facsimile transmission and electronic mail. Any signature affixed to this Agreed Order shall constitute an original signature for all purposes and may be used, filed, substituted, or issued for any purpose for which an original signature could be used. The term "signature" shall include manual signatures and true and accurate reproductions of manual signatures created, executed, endorsed, adopted, or authorized by the person or persons to whom the signatures are attributable. Signatures may be copied or reproduced digitally, electronically, by photocopying, engraving, imprinting, lithographing, electronic mail, facsimile transmission, stamping, or any other means or process which the Executive Director deems acceptable. In this paragraph exclusively, the terms "electronic transmission", "owner", "person", "writing", and "written" shall have the meanings assigned to them under TEX. BUS. ORG. CODE § 1.002.
- The Chief Clerk shall provide a copy of this Agreed Order to each of the parties. By law, the effective date of this Agreed Order is the third day after the mailing date, as provided by 30 Tex. Admin. Code § 70.10(b) and Tex. Gov't Code § 2001.142.

E. I. du Pont de Nemours and Company DOCKET NO. 2014-0377-AIR-E Page 6

SIGNATURE PAGE

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

For the Commission	
For the Executive Director	10/8/14 Date
du Pont de Nemours and Company. I am aut behalf of E. I. du Pont de Nemours and Cor	the attached Agreed Order in the matter of E. I horized to agree to the attached Agreed Order or npany, and do agree to the specified terms and EQ, in accepting payment for the penalty amount
waives certain procedural rights, including, it violations addressed by this Agreed Order, revidentiary hearing, and the right to appeal. I	d Order, E. I. du Pont de Nemours and Company out not limited to, the right to formal notice of notice of an evidentiary hearing, the right to ar agree to the terms of the Agreed Order in lieu of constitutes full and final adjudication by the agreed Order.
 and/or failure to timely pay the penalty amoun A negative impact on compliance histor Greater scrutiny of any permit applicati Referral of this case to the Attorney additional penalties, and/or attorney fe Increased penalties in any future enforced Automatic referral to the Attorney Genand TCEQ seeking other relief as authorized 	ry; ions submitted; General's Office for contempt, injunctive relief, es, or to a collection agency; cement actions; neral's Office of any future enforcement actions; I by law. I documents may result in criminal prosecution.
Signature	JUNE 2, 2014 Date
Name (Printed or typed) Authorized Representative of E. I. du Pont de Nemours and Company	SITE MANAGER Title

Instructions: Send the original, signed Agreed Order with penalty payment to the Financial Administration Division, Revenue Operations Section at the address in Section III, Paragraph 1 of this Agreed Order.

Attachment A

Docket Number: 2014-0377-AIR-E SUPPLEMENTAL ENVIRONMENTAL PROJECT

Respondent:	E. I. du Pont de Nemours and Company
Penalty Amount:	Twenty-Five Thousand Dollars (\$25,000)
SEP Offset Amount:	Twelve Thousand Five Hundred Dollars (\$12,500)
Type of SEP:	Contribution to a Third-Party Pre-Approved SEP
Third-Party Administrator:	Texas Congress of Parents and Teachers dba Texas PTA
Project Name:	Texas PTA Clean School Bus Replacement Program
Location of SEP:	Statewide, with preference for Texas Air Quality Control Region 106: Southern Louisiana - Southeast Texas

The Texas Commission on Environmental Quality ("TCEQ") agrees to offset a portion of the administrative penalty amount assessed in this Agreed Order for the Respondent to contribute to a Supplemental Environmental Project ("SEP"). The SEP Offset Amount is set forth above and such offset is conditioned upon completion of the project in accordance with the terms of this Attachment A.

1. Project Description

a. Project

The Respondent shall contribute the SEP Offset Amount to the Third-Party Administrator named above. The contribution will be to the **Texas Congress of Parents and Teachers dba Texas PTA** for the *Texas PTA Clean School Bus Replacement Program*. The contribution will be used in accordance with the SEP between the Third-Party Administrator and the TCEQ (the "Project"). Specifically, the contribution will be used to reduce nitrogen oxides, volatile organic compounds, carbon monoxide, and particulate matter emissions by replacing older diesel buses with newer buses that meet more stringent emission standards. The Third-Party Administrator shall use the SEP Offset Amount for up to 100% of the purchase price of a model year 2010 or newer bus to replace a diesel school bus that is model year 2002 or older. The SEP will be done in accordance with all federal, state, and local environmental laws and regulations.

All dollars contributed will be used solely for the direct cost of the Project, including but not limited to supplies, materials, and equipment. Any portion of this contribution that is not spent on the specifically identified SEP may, at the discretion of the Executive Director ("ED"), be applied to another pre-approved SEP.

E. I. du Pont de Nemours and Company Agreed Order - Attachment A

The Respondent's signature affixed to this Agreed Order certifies that it has no prior commitment to make this contribution and that it is being contributed solely in an effort to settle this enforcement action. The Respondent shall not profit in any manner from this SEP.

b. Environmental Benefit

This SEP will directly benefit air quality by reducing harmful exhaust emissions which contribute to the formation of ozone and may cause or exacerbate a number of respiratory diseases, including asthma. In addition, by encouraging less school bus idling, this SEP contributes to public awareness of environmental matters.

c. Minimum Expenditure

The Respondent shall contribute at least the SEP Offset Amount to the Third-Party Administrator and comply with all other provisions of this SEP.

2. Performance Schedule

Within 30 days after the effective date of this Agreed Order, the Respondent must contribute the SEP Offset Amount to the Third-Party Administrator. The Respondent shall make the check payable to **Texas Congress of Parents and Teachers SEP** and shall mail the contribution with a copy of the Agreed Order to:

Texas PTA 408 West 11th Street Austin, Texas 78701

3. Records and Reporting

Concurrent with the payment of the SEP Offset Amount, the Respondent shall provide the Enforcement Division SEP Coordinator with a copy of the check and transmittal letter indicating full payment of the SEP Offset Amount due to the Third-Party Administrator. The Respondent shall mail a copy of the check and transmittal letter to:

Texas Commission on Environmental Quality Enforcement Division Attention: SEP Coordinator, MC 219 P.O. Box 13087 Austin, Texas 78711-3087 E. I. du Pont de Nemours and Company Agreed Order - Attachment A

4. Failure to Fully Perform

If the Respondent does not perform its obligations under this Attachment A, including full expenditure of the SEP Offset Amount and submittal of the required reporting described in Sections 2 and 3 above, the ED may require immediate payment of all or part of the SEP Offset Amount.

In the event the ED determines that the Respondent failed to fully implement and complete the Project, the Respondent shall remit payment for all or a portion of the SEP Offset Amount, as determined by the ED, and as set forth in the attached Agreed Order. After receiving notice of failure to complete the SEP, the Respondent shall include the docket number of the attached Agreed Order and a note that the enclosed payment is for the reimbursement of a SEP; shall make the check payable to "Texas Commission on Environmental Quality;" and shall mail it to:

Texas Commission on Environmental Quality Litigation Division Attention: SEP Coordinator, MC 175 P.O. Box 13087 Austin, Texas 78711-3087

5. Publicity

Any public statements concerning this SEP made by or on behalf of the Respondent, must include a clear statement that **the Project was performed as part of the settlement of an enforcement action brought by the TCEQ**. Such statements include advertising, public relations, and press releases.

6. Clean Texas Program

The Respondent shall not include this SEP in any application made to TCEQ under the "Clean Texas" (or any successor) program(s). Similarly, the Respondent may not seek recognition for this contribution in any other state or federal regulatory program.

7. Other SEPs by TCEQ or Other Agencies

The SEP Offset Amount identified in this Agreed Order has not been, and shall not be, included as a SEP for the Respondent under any other Agreed Order negotiated with the TCEQ or any other agency of the state or federal government.